

Test Report No. <u>9853/17</u> Sassuolo, 21/03/18

Requested by:		GAMBINI GROUP S.p.A. Via Radici in Piano, 675 – 41049 SASSUOLO (MO)						
For the sample:	e: Glazed ceramic tiles 35,5 x 71 x 0,9 cm marked "Articolo MARMI CARRARA BIANCO 35,5x71 cm".							
On (date): 27/12/17		Date of receipt in laboratory (sample delivered by the client): 12/12/17						
Test date		From: 12/02/18	То:	12/02/18				

EN ISO 10545-4 - Determination of modulus of rupture and breaking strength

d - diameter of rods (mm):	20
t - thickness of rubber (mm):	5
I - overlap of tile beyond the edge supports (mm):	11
L - span of the support rods (mm):	690

Test specimens	1	2	3	4	5	6	7
F – Breaking load (N)	1009	970	997	993	996	1007	986
S – Breaking strength (N)	1955	1880	1932	1924	1931	1952	1912
R – Modulus of rupture (N/mm²)	45,8	44,1	44,2	45,1	44,1	44,6	44,8

F – Average Breaking load (N): 994

S – Average Breaking strength (N): 1927

R – Average Modulus of rupture (N/mm²): 44,7

Eng. Giordana Carani Technical approval

Prof. Maria Chiara Bignozzia

The results reported relate only to the samples tested. No responsibility is taken for the accuracy of the sampling unless it is done under our own supervision. The reproduction of this test report is only authorized in the form of a complete photographic facsimile. Our written approval is necessary for any partial reproduction. This test report consists of 1 pages, this cover included.