

Test Report No. <u>9889/17</u> Sassuolo, 21/03/18

Requested by:	GAMBINI GROUP S.p.A. Via Radici in Piano, 675 – 41049 SASSUOLO (MO)						
For the sample:	the sample: Glazed ceramic tiles 35,5 x 71 x 0,9 cm marked "Articolo MARMI LATINA CREMA 35,5x71						
On (date): 27/12/17		Date of receipt in laboratory (sample delivered by the client): 12/12/17					
Test date		From: 10/01/18	To: 11/01/18				

## EN ISO 10545-14 - Determination of stain resistance

Test solutions	Resistance class					
Stains	Test specimen 1	Test specimen 2	Test specimen 3	Test specimen 4	Test specimen 5	
Chrome green in light oil	4	4	4	4	4	
lodine (alcoholic solution 13g/l)	5	5	5	5	5	
Olive oil (def. Olive Oil Agreement - 1979)	4	4	4	4	4	

Stain resistance class - References

Resistance class 1: Stain not removed.

Resistance class 2: Stain removed by dipping in a suitable solvent for 24 hours.

Resistance class 3: Stain removed by mechanical cleaning and strong cleansing agent. Resistance class 4: Stain removed by manual cleaning with weak cleansing agent .

Resistance class 5: Stain removed by means of hot current water for 5 min.

Eng. Giordana Carani
Technical approval

Prof. Maria Chiara Bignozzi

Director

The results reported relate only to the samples tested. No responsibility is taken for the accuracy of the sampling unless it is done under our own supervision. The reproduction of this test report is only authorized in the form of a complete photographic facsimile. Our written approval is necessary for any partial reproduction. This test report consists of 1 pages, this cover included.